

Appl. No.: 10/691,803

Amdt. Date: May.22, 2006

Reply to: the Office Action of Feb. 22, 2006

Amendments to the specification

Please replace paragraph [0004] with the following amended paragraph:

[0004] However, the through holes 910 render a layout of circuit paths in the PCB 91 inconvenient. Furthermore, the frame 98a has a configuration occupying relatively large real estate on the PCB 91. US Pat. Nos. ~~6,466,446~~ 6,466,443, 6,449,157 and 5,854,738 each have similar shortcoming as stated above.